WITTENBORG

TECHNICAL INFORMATION

TYPE NO	TYPE	T.I.-NO
FB 5100	**Freshbrewer**	**… 08/02**

SERIAL NUMBERS AFFECTED **From February 2002**	ISSUED BY **Documentation/ Wittenborg ……**
SUBJECT **Changed filter plate**	ISSUED FOR (X): Action ; Information x

- **COMPONENTS CONCERNED**
  29604500 Filter plate

MODIFICATION

- In machines supplied from February 2002, the coffee filter plate has been changed and introduced into all the above mentioned models.

  Previously, the letters "OP" in the center of the filter foil were etched in full line into the foil.



  On new filter foils dots are used in the process of etching the letters into the foil.



REASON

- In the previous types, the small label "OP" in the center of the plate was found to be the weak part of the coffee filter plate. On rare occasions it has happened that the center part of the O or the P has broken off and fallen out after long or heavy-handed use. With the use of dots in the etching process instead full line etching, the letters are much less likely to wear and fall out.

CONTACT PERSON

- Technical
  Jes E. Rasmussen

  Spare parts
  Customer Service

06.11.02	Trille K. Kristensen	12.11.02	Jes Erik Rasmussen
DATE :	PRODUCED BY :	DATE :	CHECKED BY :